



183 E Palm St



We do not have a picture of this house yet.
[Let us know](#) if you have one!

APN: 5833-019-035
AHAD ID: 15803
Year Built: 1916 (actual)
Legal Description: W 1/2 Lot 19, Map #3
Quadrant: Not on File
Current Lot Size: Not on File
Historic Name: Not on File
Style: Craftsman
Stories: 2
Type: Residence
CHRS: 3CS
Architect: Harmon, J.A. (confirmed)
Builder: Harmon, J.A. (confirmed)
Building Permits: None on File
Alterations: None on File
Original Owner: Pringle, Alice (Spouse: W.O.)
Original Owner Occupation: Not on File
Place of Business: Not on File
Other Owners:

| Name | Years | Comment |
|-------------------|-------|---------|
| Gibbs, Dwight A. | 1922 | N/A |
| Siegel, Bugsy (?) | N/A | N/A |
| YMCA | N/A | N/A |

Original Cost: \$4,609



183 E Palm St

Original Lot Size: Not on File

Moved on to Property: N

Former Addresses:

| Address | Years |
|------------------------------------|-------|
| Palm nr Marengo Altadena, CA 91001 | 1916 |
| 119 E. Palm Altadena, CA 91001 | N/A |

Address Notes: Not on File

Note:

May have once been pt. of Way prop. (3079 Highview) before house was built; 6 rms., 40x48, frame, garage; reportedly, Italian plantings done by Luther Burbank & Theodore Payne; Caudill (474 W. Loma Alta) may have documentation on Burbank visit; 205 E. Pal

Sources:

Builder & Contractor (journal) 5/11/16, p. 23

Builder & Contractor (journal) 8/17/16, p. 19 (NofC)

Astrid Ellersieck

Information from William Wilson Co. real estate files

California Historical Resource Status (CHRS) Codes Key

| Code | Description |
|------|---|
| 1S | Individual property listed in National Register by the Keeper. Listed in the California Register. |
| 3CD | Appears eligible for California Register as a contributor to a California Register eligible district through a survey evaluation. |
| 3CS | Appears eligible for California Register as an individual property through survey evaluation. |
| 3S | Appears eligible for National Register as an individual property through survey evaluation. |

Do you find this property data informative and useful? Consider [supporting Altadena Heritage](#).